


Amended Preferential Runway System

Quarterly Report


January to March 2023 (Q1 2023)

Amended Preferential Runway System

1st Choice - Whenever crosswind, tailwinds & winds-aloft allow




2nd Choice - Whenever crosswind, tailwinds & winds-aloft allow




Selection driven by weather conditions and infrastructure availability when 1st or 2nd choice are not operable. Ultimately any single or pair of runways can be used.


Operation for northerly wind




Operation for southerly wind



Operation for westerly wind



Operation for easterly wind



Key:

← Primary departures

← Primary arrivals

↔ Maintenance adjusted departures

↔ Maintenance adjusted arrivals

Adherence and Non-Adherence Meaning



- Operations that occur on the 1st or 2nd choice runways, or their maintenance adjusted counterparts, are considered to have adhered to the Preferential Runway System.
- When the 1st or 2nd choice are not operable, the wind dictated runway(s) or the maintenance adjusted counterpart(s) will be used. These are still part of the Preferential Runway System and are therefore considered as adherent.
- Non-adherent operations can occur when an aircraft arrives or departs off a runway that isn't part of the 1st, 2nd or wind driven runways that are in use at that time. This could happen as a result of:
 - Heavy traffic caused by a weather event earlier in the day requiring the use of additional runways (e.g. due to winds Runway 33R is being used for arrivals and departures, however some arrivals are offloaded onto Runway 33L. These offloads are considered non-adherent).
 - A medevac aircraft requesting the use of a non-preferential runway for safe and expedited patient transport (e.g. departed Runway 23 when the 1st choice was being used).
 - The aircraft was assigned a runway before the start of the preferential runway hours but ended up operating after midnight (e.g. aircraft already lined up for departure off Runway 23, cleared to take off even though the airport had just switched to the 1st choice configuration).
 - An active runway is temporarily unavailable due to snow clearing or a bird strike (e.g. the 1st choice configuration is in use, but during snow clearing on Runway 05, several aircraft arrive on Runway 06L and are considered non-adherent).

Monthly Adherence – January to March 2023




YTD 2023		
Month	Adhered	Non-Adhered
January	85.4%	14.6%
February	86.2%	13.8%
March	97.0%	3.0%
Total	89.9%	10.1%


Adherence Breakdown - January to March 2023




All Movements




Arrivals



Departures




Runway Usage - January to March 2023



Primary Configuration by Hours - January to March 2023



This chart shows the percent of total hours spent in each configurations listed below. This only reflects the primary configuration in use at the time and does not mean that all operations during that hour used that configuration. For example, the hour may have had a non-adherent operation that occurred on a different runway, or a change in winds towards the end of the hour may have required a runway change.



Arr	Dep	Configuration
05	33R	1st Choice
06L	33R	1st Choice (maintenance)
06L	33L	1st Choice (maintenance)
05	33L	1st Choice (maintenance)
15L	23	2nd Choice
15R	23	2nd Choice (maintenance)
15L	24R	2nd Choice (maintenance)
15R	24R	2nd Choice (maintenance)
05	05	Easterly
06L	06L	Easterly (maintenance)
23	23	Westerly
24R	24R	Westerly (maintenance)
15L	15L	Southerly
15R	15R	Southerly (maintenance)
33R	33R	Northerly
33L	33L	Northerly (maintenance)